Cardiovascular Medicine

Images in Cardiovascular Medicine | Published 11 April 2020 | doi:10.4414/cvm.2020.02016 Cite this as: Cardiovasc Med. 2020;23:w02106

Fusiform mid-LAD aneurysm due to passive arterial wall dilatation after implantation of a self-expandable stent

Negro Alessandro^a, Biasco Luigi^b, Pedrazzini Giovanni^c, Moccetti Marco^c

^a FMH Internal Medicine, FMH Cardiology, Sementina, Switzerland

^b Ciriè and Ivrea Hospitals, ASL TO4, Italy

^c Cardiocentro Ticino, Lugano, Switzerland

Coronary artery aneurysm formation following percutaneous coronary intervention (PCI) with drug-eluting stents is a known, infrequent complication, causing late acquired strut malapposition, a potential trigger for in-stent thrombosis [1]. First generation durable-polymer sirolimus-eluting stents showed a significant association with coronary evaginations on optical coherence tomography (OCT), probably related to the inflammatory and durable polymer [2].


The Xposition S is a sirolimus-eluting self-apposing coronary stent with a durable polymer that, by passively adapting to variances in vessel diameter, allows for maximal stent apposition.

We herein report the case of a late acquired fusiform aneurysm of the mid-left anterior descending artery (LAD) caused by the passive arterial wall dilatation as a consequence of the implantation of aself-expandable stent.

A 61-year-old patient, with known coronary artery disease, underwent PCI with a self-expandable stent (Stentis XPO-SITION S $3.5-4.5 \times 27$ mm) for an anterior non-ST segment elevation myocardial infarction (NSTEMI) in January 2016. Post-implant OCT showed good apposition of the stent, with a mean vessel diameter of 3.57 mm at the distal edge and 3.67 mm at the proximal edge (fig. 1)

Because of recurrent angina, check-up angiography was performed in March 2018. A fusiform aneurysm of the mid-LAD was discovered. Intravascular ultrasound revealed a uniform dilatation of the vessel with a calibre of 6 mm throughout the whole stented segment, with no ev-

Figure 1: Post-implant optical coherence tomography (January 2016): good apposition of the stent with a mean vessel diameter of 3.57 mm at the distal edge and 3.67 mm at the proximal edge.



Correspondence: Alessandro Negro, MD, Medical Village, Via Cantonale 38, CH-6928 Manno, negro.alessandro[at]yahoo.it

Cardiovascular Medicine · PDF of the online version · www.cardiovascmed.ch

Published under the copyright license "Attribution – Non-Commercial – No Derivatives 4.0". No commercial reuse without permission. See http://emh.ch/en/services/permissions.html.




Figure 2: Intravascular ultrasound (March 2018): evidence of fusiform aneurysm of the mid-left anterior descending artery, with uniform dilata-

idence of late acquired malapposition (fig. 2), confirming angiographic findings.

This case represents a new, previously undescribed complication after implantation of self-expandable stent, which caused passive arterial wall dilatation.

Disclosure statement

No financial support and no other potential conflict of interest relevant to this article was reported.

References

- Alfonso F, Pérez-Vizcayno MJ, Ruiz M, Suárez A, Cazares M, Hernán-1 dez R, et al. Coronary aneurysms after drug-eluting stent implantation: clinical, angiographic, and intravascular ultrasound findings. J Am Coll Cardiol. 2009;53(22):2053-60. doi: http://dx.doi.org/10.1016/ j.jacc.2009.01.069. PubMed.
- 2 Radu MD, Räber L, Kalesan B, Muramatsu T, Kelbæk H, Heo J, et al. Coronary evaginations are associated with positive vessel remodelling and are nearly absent following implantation of newer-generation drugeluting stents: an optical coherence tomography and intravascular ultrasound study. Eur Heart J. 2014;35(12):795-807. doi: http://dx.doi.org/ 10.1093/eurheartj/eht344. PubMed.

Cardiovascular Medicine · PDF of the online version · www.cardiovascmed.ch